PREAKNESS & LIBRARY ANNEX

1006 HAMBURG TURNPIKE

KEY:	TNR: TESTING NOT REQUIRED	
	DEP & EPA STANDARD LEAD LEVEL: < 15.000 PARTS PER BILL	
	ND: None Detected BS: Below DEP / EPA Standard	

SAMPLE NUMBER	SAMPLE DESCRIPTION / LOCATION	FIRST DRAW TEST RESULTS
L6444473-1	FOUNTAIN MAIN ENTERANCE	< 0.00050
L6444473-2	SINK ROOM # 2	4.09
L6444473-3	MAIN OFFICE SINK	<15 ppb
L6444473-4	SECOND FLOOR FOUNTAIN	>15 ppb
L6444473-5	FOUNTAIN IN PRE K-9	1.23
L6444473-6	LIBRARY CONFERENCE ROOM	5.86
L6444473-7	STORAGE ROOM SINK NEXT TO PRE K- 9	1.46
L6444473-8	LIBRARY FOUNTIAN	<15 ppb
L6444473-9	MAIN ROOM SINK NEXT TO GIRLS ROOM	2.62
L6444473-10	FOUNTAIN BY PRE K-3	< 0.00050

ION
Test Date 12/7/2016 & 4/26/17
REMEDIAL ACTION NOTES
BS
BS
BS
Disconnected Outlet
BS
BS
BS
BS
BS
BS